EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	323/255.cds. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 09:58
L2	15	(variable adj frequency adj generator) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:01
L3	0	(variable adj frequency adj generator).ti. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:01
L4	44	(series with parallel with converter with (dc "dc-dc" "dc/dc" "dc-to-dc")) and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:02
L5	1	307/71.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:05
L6	60	(transformer same windings same fault) and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:06
L7	0	((transformer same windings same fault same (step-down (step adj down))) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:07

L8	3	(transformer same harmonic same cancel) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:08
L9	48	(gas adj turbine) same converter and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:08
L10	2	(gas adj turbine) same converter same transformer and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:08
L11	1	transformer with (harmonic near3 current) with cancel and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:09
L12	0	307/71.ccls. and ((current- control or (current adj control)) adj mode) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:10
L13	1	307/71.ccls. and ((current- control or (current adj control))) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:10
L14	4	323/255.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:10
L15	1	323/256.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:11

L16	5	361/20.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:12
L17	4	361/35.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:13
L18	6	361/38.ccls. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:14
L19	0	307/54.ccls. and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:14
L20	2	307/58.cds. and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:14
L21	0	307/61.ccls, and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:15
L22	8	307/82.ccls. and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:15
L24	0	(transformer same (fault adj winding)) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:16

L25	0	(transformer and (fault adj winding)) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:16
L26	509	(generator same (gas adj turbine)) and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:17
L27	383	(generator with (gas adj turbine)) and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:17
L28	105	(generator with (gas adj turbine)) and power.ti. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:17
L29	21	(generator with (gas adj turbine)) and power.ti. and converter and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:17
L30	178	(generator with (gas adj turbine)) and (generator turbine).ti. and @pd> = "20071004"	US-PCPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:18
L31	7	(generator with (gas adj turbine)) same (startup start-up) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:18
L32	3	(generator with (gas adj turbine)) same (startup start-up) and power.ti. and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:19

L33	2	(((selectively adj coupled) selectively-coupled) near3 winding) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:21
L34	2	(((selectively adj coupled) selectively-coupled) near3 winding) and transformer and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:21
L35	2	winding near3 ((selectively adj coupled) selectively- coupled) and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:22
L36	7	(wind adj turbine) same (prime adj mover) and @pd>="20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:22
L37	1	323/345.ccls. and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:23
L38	0	323/346.ccls. and @pd> = "20071004"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/24 10:23
L39	1	(converter and series and parallel and mode and transformer and primary and (fault adj winding) and (sensing sensor monitoring) and (voltage current)).clm.	US-PGPUB	OR	ON	2008/03/24 10:25
L40	1	(converter and series and parallel and transformer and primary and (fault adj winding) and (sensing sensor monitoring) and (voltage current)).clm.	US-PGPUB	OR	ON	2008/03/24 10:25

L41	2	(converter and series and parallel and transformer and primary and normal and fault and winding and (sensing sensor monitoring) and (voltage current)).clm.	US-PGPUB	OR	ON	2008/03/24 10:25
L42	4	(converter and series and parallel and transformer and primary and fault and winding and (sensing sensor monitoring) and (voltage current)).clm.	US-PGPUB	OR	ON	2008/03/24 10:28
S76	34	(zigzag adj transformer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/22 17:24
S77	1	S76 and (fault adj winding)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/22 17:24

^{3/24/2008 11:02:21} AM

C:\ Documents and Settings\ hkaplan\ My Documents\ EAST\ Workspaces\ 10813823.wsp